



Vehicle Condition Report

2020 INTERIONAL MV607

Vehicle Information

Inspection Date	10/25/2024 5:34 AM	AutoGrade	2.60
Stock Number	78069664	Odometer Reading	260,126
VIN	3HAEUMML3LL697995	Exterior Color	WHITE
Year	2020	Interior Color	Charcoal
Make	INTERIONAL	Body Style:	Other - 2 Door Vehicle
Model	MV607	Driveable:	No


Vehicle Damages

Damage Photo	Damage Item	Damage Type	Damage Severity
	Left Front Door	Heavy Scratch	< 1/8 inch
	Overall Vehicle	Multiple Scratches Light	10 or more
	Right Front Door	Heavy Scratch	> 12 inches

Tire Condition

Left Front Tire	14/32	Right Front Tire	14/32
Left Rear Tire	14/32	Right Rear Tire	14/32

Vehicle Photos


























Factory Options

Standard Equipment

